ACCOUNT TITLE

<u># Maintenance & Replacement Projects</u>	2011/12	2012/13	2013/14	2014/15	2015/16	2017+
<u>CAMPUS</u>						
1 Roof Repairs – According to PSI Report 2009	77,000	8,000				
2 Boiler Inspection and Tube Replacement	50,000					
SHW to update the Facilities Assessment, 5-Year Master Plan, and 3 Campus Master Plan.	15,000		25,000			
4 GIS & Utility Mapping			25,000			
5 Ditch Cleaning			20,000			
Occupancy Sensors - Install occupancy sensors in classrooms to 6 control lighting			10,000			
Replace building air handling unit chilled water coil control valves - 7 Ad, CLRC, LS, ET, & WT (Facilities Assessment 2009)				82,000		
Campus - Rehabilitate existing underground piping (Campus Chilled 8 Water and Boiler Study)						490,000
9 Campus Signage: Way-Finding						100,000
Subtotal for CAMPUS	142,000	8,000	80,000	82,000	-	590,000
ADMINISTRATION BUILDING						
10 Room 173C Foundation Repair	60,000					
11 Ad Building - repointing and sealant replacement on new wing.	20,000					
Ad Building - Air Handler drain pan replacements (Facilities 12 Assessment 2009)			15,000			
13 Bookstore Renovation (31 Fund)						180,000
Replace Admin entrance doors and vestibule doors. The door frames and hardware are worn and some entrances are not ADA compliant.14 (Facilities Assessment report 2009)						70,000
SSA 12 x 12 ceilings are in need of replacement. (Facilities 15 Assessment Report 2009)						46,000
Ad Building - glazing sealant replacement. (Facilities Assessment 16 2009)						29,000
Subtotal for ADMINISTRATION BUILDING	80,000	-	15,000	-	-	325,000
<u>CLRC</u>						
17 IS Backup Generator			200,000			L

ACCOUNT TITLE

# Maintenance & Replacement Projects	2011/12	2012/13	2013/14	2014/15	2015/16	2017+
Replace all fogged over windows 1st and 2nd floor, and entrance 18 doors CLRC Bldg. (Facilities Assessment Report 2009)				220,000	220,000	
CLRC Basement Waterproofing - Eliminate existing moisture				220,000	220,000	
19 infiltration (Facilities Assessment Report 2009)					37,000	
20 Refurbish interior stairwells-CLRC						40,000
Subtotal for CLRC	-	-	200,000	220,000	257,000	40,000
HEALTH EDUCATION BUILDING						
WHEB composite metal exterior wall panels require sealant						
21 replacement. (Facilities Assessment 2009)				27,000		
22 Refinish Floors - HEB Gym & Dance Floor						6,000
Subtotal for HEALTH EDUCATION BUILDING	-	-	-	27,000	-	6,000
LA-Z-BOY CENTER						
23 LZBC Flashing Repair	50,000	50,000				
LZBC - Masonry joints in need of tuck pointing. (Facilities						
24 Assessment 2009)				60,000		
LaZBoy Glazing repairs where windows meet metal panel system.						07.000
25 (Facilities Assessment 2009)						27,000
26 Refinish Floors - La Z Boy Theater						12,000
Subtotal for LA-Z-BOY CENTER	50,000	50,000	-	60,000	-	39,000
LIFE SCIENCES BUILDING						
Life Science Office carpet at end of useful life. (Facilities Assessment				00.000		
27 2009)				22,000		
LS Building - Replace P-Valves and isolation valves and stats in						
original building room re-heat units. Systems have begun to fail and						
28 are inoperable. (Facilities Assessment Report 2009)					25,000	
LS 12 x 12 ceilings are in need of replacement. (Facilities Assessment 29 Report 2009)						43,000
30 Refurbish interior stairwells-LS						40,000
Subtotal for LIFE SCIENCES BUILDING	-			22,000	25,000	83.000
EAST TECH	-	-	-	22,000	23,000	03,000
EASTIEUT						

ACCOUNT TITLE

<u># M</u>	aintenance & Replacement Projects	2011/12	2012/13	2013/14	2014/15	2015/16	2017+
	- Replace P-Valves and isolation valves and stats in ding room re-heat units. Systems have begun to fail and						
	ble. (Facilities Assessment Report 2009)				15,000		
Subtotal for EAS	ST TECH	-	-	- 1	15,000	-	-
	WEST TECH						
	eam Valves in WT Building – Electric Operators, increased						
32 efficiency, r	educe lost steam			25,000			
	 Deplete D Mehrer and instation values and state in 						
	g - Replace P-Valves and isolation valves and stats in ding room re-heat units. Systems have begun to fail and						
	ble. (Facilities Assessment Report 2009)				15,000		
Subtotal for WE		-	-	25,000	15,000	-	-
	WHITMAN CENTER						
	enter - Replace T12 Ballasts in classrooms, 215 fixtures.						
34 (Facilities A	ssessment Report 2009)	65,000					
35 Repair, sea	I coat and re-stripe Whitman			35,000			
	enter plastic laminates need to be replaced and window placed. (Facilities Assessment Report 2009)			30,000			
	ITMAN CENTER	65.000		65.000			
	SALT STORAGE	05,000	-	00,000	1	-	-
Maintenand	ce Salt Building Replacement (Facilities Assessment						
37 Report 200							10,000
Subtotal for SAL	T STORAGE	-	-	-	-	-	10,000
	DRIVES AND LOTS						
38 Repair, sea	I coat and re-stripe Lots 7			55,000			
39 Repair, sea	I coat and re-stripe Lots 3 and 4				75,000		
40 Replace ex	terior lighting conduits and light poles						350,000
41 Mill and Ov	erlay Drive on Main Campus. Asphalt is deteriorating.						250,000
Subtotal for DRI	VES AND LOTS	-	-	55,000	75,000	-	600,000
	<u>BR200</u>						
	illers installed in 1978 – Learning Resource Center boiler						
room BR20 42 Water and	0 (Facilities Assessment Report 2009) (Campus Chilled			480,000			
Subtotal for BR2		-	-	480,000	-	-	
SUDIOIALIOL BRA	200	-	-	400,000	-	-	-

ACCOUNT TITLE

<u># Maintenance & Replacement Projects</u>	2011/12	2012/13	2013/14	2014/15	2015/16	2017+
BR100						
Replace boilers installed in 1978 – Life Science Building boiler room BR100 (Facilities Assessment Report 2009) (Campus Chilled Water						
43 and Boiler Study)				410,000		
Subtotal for BR100	-	-	-	410,000	-	-
<u>BR300</u>						
Replace boilers installed in 1978 – Administration Building boiler room BR300 (Facilities Assessment Report 2009) (Campus Chilled Water						
44 and Boiler Study)					410,000	
Subtotal for BR300	-	-	-	-	410,000	-
PHYSICAL PLANT						
Phys Plant - Replace existing cooling towers and condenser waterpumps (Campus Chilled Water and Boiler Study)					420,000	
Phys Plant - replace indoor chiller, CHW pumps (Campus Chilled 46 Water and Boiler Study)						870,000
Phys Plant - upgrade existing electrical service (Campus Chilled 47 Water and Boiler Study)						130,000
Subtotal for PHYSICAL PLANT	-	-	-	-	420,000	1,000,000
HURD ROAD						
48 Fence	6,000					
Subtotal for HURD ROAD	6,000	-	-	-	-	-

Totals: \$343,000.00 \$58,000.00 \$920,000.00 \$926,000.00 \$1,112,000.00 \$2,693,000.00